



HEALTH HAZARD DATA

INHALATION AND SKIN ABSORPTION HEALTH RISKS: OSHA permissible concentration of mineral oil mist in air is 5 mg/m³.

SKIN AND EYE CONTACT: Prolonged contact may cause minor skin irritation.

SYMPTOMS OF EXPOSURE: N/A

INGESTION: N/A

ACUTE AND CHRONIC HEALTH HAZARDS: N/A

CARCINOGENICITY:	NTP	IARC MONOGRAPHS	OSHA REGULATED
	NO	NO	NO

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE: N/A

EMERGENCY AND FIRST AID PROCEDURES:

EYES: Flush with large amounts of water for at least 15 minutes. If redness or irritation persists, contact a physician.
SKIN CONTACT: Wash with soap and water.
INHALATION: None normally required.
INGESTION: Call a physician.

PRECAUTIONS/CONTROL MEASURES FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE OF RELEASE OR SPILL: Stop leak. Dike up large spills. Use inert absorbant materials such as earth, sand or vermiculite for clean-up.

WASTE DISPOSAL METHOD: Dispose of in accordance with Federal, State, and Local regulations.

PRECAUTIONS FOR STORAGE AND HANDLING: Avoid exposure to heat and flames. Protect against eye and skin contact.

WORK/HYGIENIC PRACTICES: Wash thoroughly after handling.

DISCLAIMER

INFORMATION AND RECOMMENDATIONS CONTAINED HEREIN ARE BELIEVED TO BE ACCURATE AT THE TIME OF PREPARATION. NO WARRANTY IS MADE CONCERNING THE ACCURACY AND NO LIABILITY SHALL BE MADE FOR CLAIMS FOR USE OR RELIANCE OF THE RECOMMENDATIONS CONTAINED HEREIN.